Scope of	Work for Prope	rty Locate	ed at	:	<u>284</u>	7 North 36th Street		
	Property is: Sin	ngle Family	~	Duplex		Other		
Date:	8/31/2015							
ake no respo	onsibility for problems dis	scovered after	the in	spection da	ate, or fo	City of Milwaukee, the Redevelopment A or omissions through error or oversight. ock Grant or HOME programs.	•	
Exterior	Condition Repor	t						
Location Site	Required Work Landscaping	n	/a 🗌	Yes 🗸		e/Comments tree branches/brush from building	\$	Cost 700.00
	Steps/Handrails	n	/a ✓	Yes 🗌			\$	
	Service walks	n	/a ☑	Yes 🗌			\$	
	Fencing	n	/a ✓	Yes			\$	
	Parking	n	/a	Yes 🗌			\$	
	Retaining walls	n	/a ✓	Yes 🗌			\$	
	Other	n	/a 🗌	Yes \square			\$	
	Other	n	/a 🗌	Yes 🗌			\$	
Garage	Singles: repair	n	/a 🗌	Yes 🗌			\$	
	Shingles: Roof over e	existing n	/a 🗌	Yes 🗌			\$	
	Shingles:Tear off & re	e-roof n	/a 🗌	Yes 🗌			\$	
	Gutters/downspouts	n	/a 🗌	Yes 🗌			\$	
	Flashing	n	/a 🗌	Yes 🗌			\$	
	Eaves	n	/a 🗌	Yes 🗌			\$	
	Siding	n	/a 🗌	Yes 🗌			\$	
	Doors	n	/a 🗌	Yes 🗌			\$	
	Windows	n	/a 🗌	Yes 🗌			\$	
	Slab	n	/a 🗌	Yes 🗌			\$	
	Paint	n	/a 🗌	Yes 🗌			\$	
	Electrical	n	/a 🗌	Yes 🗌			\$	
	Other	n	/a 🗌	Yes 🗸	raze	or repair to code compliant conditi	on \$	4,500.00
Porches	Roof	n	/a	Yes 🗌			\$	
	Deck-front	n	/a 🗌	Yes ✓			\$	3,200.00
	Deckrear	n	/a 🗌	Yes 🗸			\$	2,200.00
	Steps/handrails	n	/a	Yes 🗌			\$	
	Ceiling	n	/a ✓	Yes 🗌			\$	
	Guardrails	n	/a	Yes 🗌			\$	
	Structural	n	/a 🗸	Yes 🗌			\$	
	Paint	n	/a ☑	Yes 🗌			\$	

n/a 🗌 Yes 🗹 **permit**

Other

85.00

\$

House

Chimney	n/a ☐ Yes ☑	tuckpoint	\$ 200.00
Shingles: repair	n/a ☐ Yes ☑		\$ 600.00
Shingles: Roof over existing	n/a ☑ Yes 🗌		\$
Shingles:Tear off & re-roof	n/a ☑ Yes 🗌		\$
Gutters/downspouts	n/a ☐ Yes ☑		\$ 1,008.00
Flashing	n/a ✓ Yes 🗌		\$
Eaves	n/a ☐ Yes ☑	fascia/soffit	\$ 1,200.00
Siding	n/a ☑ Yes □		\$
Storm Doors	n/a ✓ Yes 🗌		\$
Prime ("main") Doors	n/a ☐ Yes ☑		\$ 700.00
Storm Windows	n/a ☑ Yes 🗌		\$
Prime ("main") Windows	n/a ☐ Yes ☑		\$ 930.00
Paint	n/a ☐ Yes ☑	previously painted surfaces	\$ 1,800.00
Foundation	n/a ☑ Yes □		\$
Electrical	n/a ☐ Yes ☑	new service	\$ 1,000.00
Other	n/a ☐ Yes ☑	front porch windows	\$ 425.00
Other	n/a ☐ Yes ☑	basement windows	\$ 600.00
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$

Exterior: Estimated Cost:* \$

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

19,148.00

Interior Co	ondition Report						
	Unit: Entire unit (single family)					Lower unit of duplex	
Mechanical	Upper unit of duplex Required Work					Other	
Heating	Required Work						
_	Repair/replace boiler	n/a	✓	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a		Yes	/		\$ 3,080.00
	Repair ductwork	n/a		Yes	V		\$ 400.00
	Replace thermostat	n/a		Yes	V		\$ 100.00
	Repair/replace grilles	n/a		Yes	V		\$ 80.00
= 1	Other	n/a		Yes	V	permit	\$ 85.00
Electrical	Repair/replace receptacles	n/a		Yes	V		\$ 800.00
	Repair/replace switches	n/a		Yes	V		\$ 800.00
	Repair/replace fixtures	n/a		Yes	V		\$ 800.00
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a		Yes	V		\$ 1,749.00
	Other	n/a		Yes	√	permit	\$ 85.00
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	~	Yes			\$
	Repair/replace kitchen sink fauce	: n/a		Yes	V		\$ 315.00
	Repair/replace tub	n/a		Yes			\$
	Repair/replace tub faucet	n/a		Yes			\$
	Repair/replace toilet	n/a		Yes			\$
	Repair/replace lavatory	n/a		Yes			\$
	Repair/replace lavatory faucet	n/a		Yes			\$
	Repair/replace wash tub	n/a	V	Yes			\$
	Repair/replace wash tub faucet	n/a	V	Yes			\$
	Unclog piping:	n/a	V	Yes			\$
	Repair drain/waste/vent piping	n/a	√	Yes			\$
	Repair water piping	n/a	V	Yes			\$
	Repair/replace water heater	n/a		Yes	V		\$ 1,300.00
	Other	n/a		Yes	√	complete bathroom	\$ 2,170.00

n/a ☐ Yes ☑ permit

\$

85.00

Other

Windows								
	Replace broken glass	n/a	V	Yes			\$	
	Repair or replace sash	n/a	V	Yes			\$	
Doors								
	Repair or replace doors	n/a		Yes	J		\$	570.00
	Repair or repl. locks/latches	n/a		Yes	✓	Self Help	\$	165.00
Walls/Ceiling					_		_	
	Repair or repl. @ defective	n/a	Ш	Yes	1		\$	1,400.00
Paint	Repair or repl. @ defective	n/a		Yes	V		\$	700.00
F: 0.4.	Tropan of Topic & dolocavo	11/4		100			Ψ	700.00
Fire Safety	Install smoke/CO alarm:bsmt.	n/a	V	Yes		Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a	V	Yes		Self Help	\$	
	Install smoke/CO alarm: 2nd flr.	. n/a	V	Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a	V	Yes		Self Help	\$	
Stairs	Repair defective	n/a	П	Yes	7	to 2nd floor (repair)	\$	500.00
Floors	Repair defective	n/a		Yes		assumed-trash covered	\$	2,100.00
Other	repair derective	11/4		163	Ľ	assumed-trasm covered	Ψ	2,100.00
		n/a		Yes			\$	
	_	n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	17,284.00
						Total Exterior and Interior Cost:*	\$	36,432.00
	*average contracted cost. Actual costs may vary. Self help will reduce the amount.							

Inspected by: Tom Frank Date: 8/27/15

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.